



ON THE  
**SAFE  
SIDE**

## ***Hot Work/Welding***

Where do these requirements apply to your workplace today?

- COMPRESSED GAS UPRIGHT POSITION + SECURED
- O<sub>2</sub> + ACETYLENE STORED 20' APART OR BARRIER
- LIFT BOTTLES WITH CARTS WITH ENGINEERED PICKING EYE
- BOTTLES HAVE PROTECTIVE CAPS
- VALVES CLOSED AT THE TORCH BEFORE TURNING ON REGULATOR VALVES
- HOSES HAVE SLASH ARRESTORS AT THE TORCH END
- CHECK FOR SIGNS OF WEAR, DAMAGE, OR LEAKS
- NO FLAMMABLE MATERIAL WITHIN 35' OF HOT WORK
- USE A FIRE WATCH - STAY 30 MINUTES AFTER COMPLETE

*Action Required: Inspect your work area with this list.*