











CRITICAL SAFE WORK HABITS

Safety Talking Points



ELECTRICAL SAFETY

-  Only qualified employees work around electricity hot.
-  Inspect & document all cord and plug equipment.
-  Cover all panels, junction boxes, misc. equipment.
-  Maintain all cord and plugs in good condition. (no frays)
-  Insure all cord & plug equipment have ground pins.
-  Insure extension cords are not used as permanent wiring.
-  Insure extension cords are not run through holes, doors, etc.
-  Keep 36" clearance in front of all panels.
-  Label all disconnects, panels, & breakers.
-  Insure all equipment grounded.



1706 Claire Court
Seneca, SC 29672
www.peakperformance.com
david.lynn@peakperformance.com
864.322.3661

Our Mission:

Help clients take their next steps in building a successful safety culture.