

Working + Walking Surfaces

Where do these requirements apply to your workplace today?

■ KEEP SURFACES FREE OF SLIP/TRIP HAZARDS
COVER ALL HOLES GREATER THAN 2"
SECURE HOLE COVERS
MARK HOLE COVERS: "HOLE COVER"
DEVELOP A CORD/HOSE MANAGEMENT PLAN
PROVIDE BARRICADE TAPE AROUND HAZARDS
PROVIDE CLEAR PATHWAYS
KEEP TRASH IN TRASHCANS
REMOVE NAILS AND PUNCTURE HAZARDS

Action Required: Inspect your work area with this list.

